	∩∩ <i>ለ/∩5/</i> // <i>ጻ</i> :< <u>‹የ</u> የተለ ፡፡-ም በ.₽.ጽ.ቁ₽ //በ₽9.8	NDORTANNATION	The state of the s
DATE 2015 Z 09 DEC 64	SECRET	1 2	9
PAGE SELLY E MA DEC 04	DECREE	3	11
		5	12
TO : DIRECTOR	ROUTEYS INT	6	14
FROM :		7 8	15 16
ACTION:			
		PRIUR	ITY
IXFO :			25X
TOR: 2306Z 09 DEC 64	10 OSA -	NR	25X ² IN 61810
TO PRIORITY INF	o PRIURITY	cm	
KEDLOCK			
1. FLIGHT NO 33 ARTICLE 1	AND FINAN R AFC 1964		0.520
	ANS LEGAIL O DEC 1304		\sim
2.			•
3. DURATION: 1:40 HRS, TO	TAL TIME: 42:05 HRS.		
4. MAX SPEED REACHED: 0.9	2 MN. MAX ALTITUDE:	5,000 FT.	
5. TIME ABOVE 2.0 M: 0:00	HRS THIS FLT. TOTAL	2:19 HRS.	
6 T. O. WEIGHT: 115,400 L	BS. C.G. 18 PERCENT.	•	
7. OBJECTIVES:			
A. EXTERNAL CAPTIVE FL	IGHI MISSILE G-II.	:	
8. ENGINE START, GENERATO	OR OPERATION, LIQUID	COOLING PACK	AGE
OPERATION, INS ALIGNMENT,	FIRE CONTROL SYSTEM	TURN ON AND	MOAT WERE
SATISFACTORY.			
SATISFACTORY. 9. THE EXTERNAL MISSILE O	CAPTIVE TEST WAS SCHE	DULED ON THE	PMR.
	:		
9. THE EXTERNAL MISSILE C	TED. THE 8-57 AUGMENT	ED WITH DOPP	PLER AND

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

25X1A

(IN 61810)

SECRET

PAGE TWO

AT 0.9 M AT 35,000 FEET.

GUDIANCE SLAVING WERE SATISFACTORY. THE MISSILE DETECTED THE TARGET AND TRACKED INTERMITTENTLY PRIOR TO ZERO TIME. AT ZERO TIME THE MISSILE LOST LOCK-ON, WAS RESLAVED AND REACQUIRED LOCK-ON. THIS SEQUENCE WAS REPEATED SEVERAL TIMES. A PITCH SLAVING ERROR WAS INDICATED WHILE THE MISSILE WAS TRACKING. THERE WAS NO DISCERNIBLE CHANGE IN TARGET AMPLITUDE, AND THE TARGET APPEARED TO BE OF CORRECT SIGNAL LEVEL. AT TRIGGERS THE TARGET WAS 10 DEGREES RIGHT AS PLANNED.

11. PASS NO 2 WAS CONDUCTED ON MISSILE POWER. THE MISSILE ACQUIRED
THE TARGET SHORTLY AFTER ZERO TIME IN THE COUNTDOWN. THERE WAS NO
INDICATION OF RECEIVER ENABLE. THE MISSILE WAS RESLAVED AND ACQUIRED
THE TARGET. PITCH SLAVING ERROR INDICATIONS WERE ZERO.

12. PASS NO 3 WAS A REPEAT OF PASS NO 2. AFTER TRANSFER TO
INTERNAL POWER THE MISSILE UNSLAVED AND THE RECEIVER WAS ENABLED.

THE MISSILE BROKE LOCK, WAS RESLAVED AND REACQUIRED THE TARGET.

DURING TRACK ZERO SLAVING ERROR WAS INDICATED. THE MISSILE TRACKED

UNTIL A LOOK ANGLE OF 30 DEGREES WAS ATTAINED. REAR REFERENCE PHASE

LOCK WAS THEN LOST WHERE UPON THE MISSILE WAS TRANSFERRED TO AIR-

CRAFT POWER. REAR REFERENCE PHASE LOCK WAS REACCOMPLISHED.

13. PASS NO 4 WAS

25X1

THE YF-12 WAS AT 0.9 M, 35,000 FEET. THE F-104

ACCELERATED, PASS THE YF-12, AND CONTINUED TO ACCEL AND CLIMB TO

1.9 M AT 45,000 FEET. IR LOCK-ON WAS ACCOMPLISHED AT 2NM. AT

SECRET

25X1